

# Oil Field Environmental Incident Summary

**Incident:** 20160314135159      **Date/Time of Notice:** 03/14/2016 13:51

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** Parshall 50-1114H

**Field Name:** PARSHALL

**Well File #:**

**Date Incident:** 3/13/2016      **Time Incident:** 11:49      **Facility ID Number:** 227205-01

**County:** MOUNTRAIL      **Twp:** 152      **Rng:** 90      **Sec:** 11      **Qtr:** SW NW

**Location Description:**

**Submitted By:** Keith Kallberg

**Received By:**

**Contact Person:** Keith Kallberg  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	4	Barrels	4	Barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

NA

**Areal Extent:**

NA

**Potential Environmental Impacts:**

NA

**Action Taken or Planned:**

The tank was isolated and the contents were removed stopping the release. Free fluids were removed from the surface of the lined containment area. The affected area will be flushed using fresh water and the fluids removed.

**Wastes Disposal Location:** Fluids were taken to SWD

**Agencies Involved:**

**Updates**

---

**Date:** 3/14/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank leak, remained within the diking according to the report. NDIC retains oversight.